

---

Subject: Re: atwater kent model 42

Posted by [Wayne Parham](#) on Sun, 04 Nov 2007 21:31:12 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Could be any number of things but I would replace the capacitors first. The capacitors in these things are usually bad, in fact, most times the tubes still work but the caps don't. Just replace every capacitor you see with a polypropylene cap of the same value. Chances are it will fire right up.

---