
Subject: Re: Montgomery Ward Airline 14BR-736 radio
Posted by [Wayne Parham](#) on Wed, 20 Aug 2008 17:05:13 GMT
[View Forum Message](#) <> [Reply to Message](#)

The hum is most likely a result of the power supply capacitors weakening. I would replace them. They're usually around 20uF, so you can swap them with new polypropylene capacitors. That will solve the hum and that kind of capacitor will last a long, long time.
