

---

Subject: mac 60

Posted by [RS](#) on Wed, 13 Jul 2005 15:36:43 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

? if the coupling caps(2eax3 35,15,80,mf@500v)? are not all the same vaule ie replacering a 44 for 35, 22 for 15 cause a bias mis match over time,sounds good for about 2hr then starts to loose output and distort. fyi,hammond now has chokes for the mac60 #159t 2.5H@300mADC.

---