

---

Subject: Re: M-50 correction

Posted by [Manualblock](#) on Wed, 24 May 2006 00:57:47 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Why not give it a shot? I didn't know much two years ago and now I can do some troubleshooting and construction. A weak channel sounds like it could be passive parts out of spec.

---