

---

Subject: Re: Philips 7831 receiver

Posted by [Wayne Parham](#) on Wed, 31 Oct 2007 17:02:38 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I think probably the output transistors for that channel have failed. Some amps have fuses on each channel as well as on the power supply, so check that all fuses in the amp are good.

---