
Subject: Re: Marantz 6350Q
Posted by [real_one](#) on Tue, 27 Nov 2007 03:11:44 GMT
[View Forum Message](#) <> [Reply to Message](#)

Sounds like the servo feedback circuit fried.
