
Subject: Re: Fisher SA-300b volume]balance Mod
Posted by [Peter Swartz](#) on Sat, 29 Dec 2007 19:30:07 GMT
[View Forum Message](#) <> [Reply to Message](#)

Thanks Wayne, Well I decided just to forget the balance pot since I had the wrong value and hope the units outputs would be balanced. So I hooked up only the 250K volume pot and had a surprise. I obviously hooked it up wrong because it works in the opposite direction. Turning the knob clockwise turns the volume down to silence and counter-clockwise makes it louder. Any suggestions? Could it be just a matter of switching the wires on the pot? It seems to work fine. And sound fine. But sure makes me wonder if it could cause some problems. Happy New Year!
Peter
