
Subject: Re: Need help fixing HRDx
Posted by [HRDnocks](#) on Tue, 24 May 2005 18:02:56 GMT
[View Forum Message](#) <> [Reply to Message](#)

My HRD had the same crackle. Turned out that it was the output transformer in the process of failing. Sounds like yours has fried too. I replaced mine with a Hammond 1620, which is conservatively rated at 20 watts, but is actually has more iron than the cheap HRD output transformer. It sounds as good or better than the fender tranny.
