Subject: Re: Don't bother with answering, seems I have found the problem Posted by Anonymous on Thu, 14 Jul 2005 15:04:04 GMT View Forum Message <> Reply to Message

Two things: speaker has great depth, was too close to power tubes. Made them vibrate. And one had a broken solder joint, which was therefore constantly moving. Fixed the soldering and removed the card board stuff from the speaker frame so that I gained some space between speaker and tubes. Thanx for reply!