

---

Subject: Fender Bandmaster Vibrato Problem

Posted by [mike d](#) on Fri, 27 Jan 2006 12:45:15 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi,I'm new on here, so appologies if this has been discussed before...butI have a 65 Bandmaster that I've had for ages, but have never had the vibrato working.I've checked the footswitch and that seems fine. When I look down one of the input jacks I can see a Valve (tube) pulseing, the speed of which changes coresponding to turning of the "speed" pot. The sound does not change however, I get a clean signal like the "normal" channel.It had a complete re-valve about 2 years ago.Any suggestions very much appreciated.Mike.p.s I last switched it off on Tuesday. Is it safe to put my hands in there yet??

---