
Subject: Re: Fender Bandmaster Vibrato Problem
Posted by [Shane](#) on Wed, 01 Feb 2006 18:15:00 GMT
[View Forum Message](#) <> [Reply to Message](#)

Years ago I finally figured out why my VibroChamp vibrato wouldn't work. It had a 12AY7 instead of a 12AX7 in it. Didn't ever look at a schematic on it and didn't realize it needed the 12AX7 in it. Vibrato went from practically non-existent to HUGE soon as I changed it.
