
Subject: Re: Fender Bass amp sound fading out
Posted by [CELT](#) on Sat, 30 Dec 2006 22:29:40 GMT
[View Forum Message](#) <> [Reply to Message](#)

More than likely bad power supply caps. Modern Fender amps seem to have a higher than normal capacitor failure rate. Another thing to check are the plastic input jacks. If the metal retainer ring has fallen out, the plug will move around and make/break contact.
