
Subject: Re: Pignose G40V Power Transformer
Posted by [Oinka](#) on Wed, 02 May 2007 11:07:06 GMT
[View Forum Message](#) <> [Reply to Message](#)

The power trans have a thermal fuse that can fail.Its possible to replace by dismantling the trans
