

---

Subject: Re: Fender 65 twin re-issue; reverb not working

Posted by [Ricardo](#) on Sun, 27 May 2007 13:40:07 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

This thread reminds me of when I bought my used Telecaster DeLuxe back in the mid seventies. The tone controls didn't seem to work, so I took the pickguard off and noticed that there were no capacitors connected to the tone pots. I took it to a friend who was much more familiar with electronics, and he said it looked like there had never been any soldering of the tone pots, and put a couple of capacitors on. I still love Fender stuff, though.

---