
Subject: Re: Fender Vibrolux Silverface '73
Posted by [Greene](#) on Mon, 24 Sep 2007 04:41:55 GMT
[View Forum Message](#) <> [Reply to Message](#)

Resolved! It was the Reverb Driver transformer breaking down. replaced and all works well.
