

---

Subject: Re: faulty reverb

Posted by [decoy](#) on Fri, 09 Nov 2007 19:00:54 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I have the same problem with my princeton, Try changing the wires that go out of the tank they should just be AV wires. If that doesn't work try changing the in wires.

---