

---

Subject: Twin Reverb Stand-by switch

Posted by [JGK](#) on Wed, 06 Feb 2008 02:17:28 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi I'm a new member and I have a 74-75 Twin Reverb. Its got a Torres Super Texan kit in it.....I know how most feel about Torres but it sounds great an I've had no problems with it for 10 years. Last week the standby switch stopped working, checked the switch its fine I'm not getting any voltage to the tubes and I have checked the circuit resisters etc and everything seems fine. It's got new filter caps that are properly installed. I was thinking maybe problems with the Transformer but if I fire up the amp with the on switch (I know it's hard on the tubes) everything works fine and my voltages AC,DC and Bias are all fine. I was hoping someone could shed a little light on the matter. Thanks JGK

---