

---

Subject: T36 in pro show

Posted by [j.luis cruz](#) . on Fri, 20 Oct 2006 14:41:20 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

As all can see the Bill itzmaurice T36 have this observations ..First the boxes are not complete , second the drivers is not the recomendated and third the width is at the minimum . still give good results with this big disaventages .

---