

---

Subject: Re: JBL SRX728S

Posted by [Tom Danley](#) on Wed, 01 Nov 2006 20:36:52 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi WaynePascal may have caught something worth checking out, perhaps there is a mic cal issue or something. Compare the measured response on the JBL web site for that sub. Your measurement is consistently higher. Compare your 100W 10M measured response for the 12 pi from last year VS this year, it is also higher. This may be from something as simple as a mic cal issue (needing a new reference Voltage setting). Tom

---