Subject: Re: Behringer Feedback Destroyer Problem Posted by Bill Fitzmaurice on Sun, 16 Oct 2005 19:46:31 GMT

View Forum Message <> Reply to Message

That's processor noise and it's quite common with feedback eliminators. You need a higher signal level going into the DSP to get a better S/N ratio. Raise it's input gain as high as will go without clipping, reduce the output level to compensate.