

---

Subject: Re:JB Weld has problems

Posted by [Bill Epstein](#) on Wed, 04 Oct 2006 23:00:44 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

You know that epoxy uses heat to cure. It took the 400 degree flash-off but shrunk. So the little repairs show up. Really looks great, overall, tho'.

---