

---

Subject: Fil PS ?

Posted by [Manualblock](#) on Fri, 04 Mar 2005 19:23:41 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Guys; the banded end of the 5408's is away from the trans correct?Also I have two 12uf Solens rated for 250v. Would they work as filter caps in the filly supply.

---