

---

Subject: Re: Too late

Posted by [Forty2wo](#) on Sat, 05 Mar 2005 03:02:25 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I think I am using the same pot RS 100k, I don't know the number. I have seen pots that were shorted but take a look with a glass and a strong light to see if there is not one strand of wire that made it's escape when it was soldered...John

---