

---

Subject: Re: the Amp

Posted by [Manualblock](#) on Sun, 06 Mar 2005 00:40:02 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Sounds good to me. Now I just need a little TLC. On the filament trans I ran one wire from the secondary to each lug on a strip then connected a diode on each lug to the secondary wires. From there I took the opposite end of both diodes and soldered them to one end of a two ohm resistor. I then took the other end of the resistor and soldered it to the pos. end of the first filter cap, with the other end of the filter cap to ground. I also grounded the CT of the RS trans. secondary. Then I took one end of the second 2 ohm resistor and tied that to the pos end of the second filter cap and ran the neg end of the cap to ground. I then took the tab with the res/cap pos end and ran a wire to pin 4 of the 5687. I then ran a wire from pin 5 to ground. Is this correct?

---