Subject: Re: Measuring current

Posted by PakProtector on Fri, 11 Mar 2005 03:20:21 GMT

View Forum Message <> Reply to Message

did it eat into your stock of spares? I would re-word a bit. Don't check between pins one and nine, repeat the measurement proceedure for pins one and nine (the anodes). If you attach negative lead to the cathode (pin 3 for pin 1 anode, and pin 6 fo the pin 9 anode) or to of the LED string, you can measure current w/o extinguishing the LED's. Not exactly remomended, as there is less room than the ground terminal offers. Thanks again Colin for teaching me that cool trick.regards, Dogulas