
Subject: Re: core geometries and materials

Posted by [PakProtector](#) on Sun, 25 Dec 2005 00:43:22 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hey-hey!!!,The strip wound, cut core also offers the ability to size the winding area to a particular design requirement. The cut core also has no portion of the magnetic path going perpendicular to the grain orientation. One can also make more than 1 set of cuts in the core. Make the individual gaps smaller, and cut down on Iron(or what ever the alloy)losses. There are lots of other neat tricks...this is just a few from the front of the book.cheers,Douglas
