

---

Subject: Re: the Schematic

Posted by [Damir](#) on Tue, 24 Jan 2006 21:21:22 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Good work! May I suggest a schematic for bias pots? Pots are 100k/lin, (50% on the scheme just means that program needs % of "opening" the pot...); in the middle position we have about -65V out. Resistors R2 & R3 (between the wiper and "input" leg of the pot) are not necessary, but it's a precaution if wiper gets discontinued. The useful range is about -50...-80V.

---