
Subject: Re: 300B SE Project, Part 7 - Common cathode 6C45Pi triode driver
Posted by [Manualblock](#) on Sun, 26 Feb 2006 20:00:04 GMT

[View Forum Message](#) <> [Reply to Message](#)

So maybe thats why the aggressive or hard sound from the driver stage? Can a CCS loaded anode be the cause of amplifier oscillation? Say; more so than a resistance loaded plate?
