
Subject: Re: whaaaaaat?

Posted by [PakProtector](#) on Sat, 04 Mar 2006 11:49:49 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hey-Hey!!!,I can say I have not encountered that sort of failure. The usual is a gate-source short on the lower MOSFET, and this is prevented by the back-to-back Zener clamps. When I have had a G-S short with a battery circuit, the short will discharge the batteries through the R-set and ~250k filter resistor. One discovers the problem quickly and a 'trace' gets lifted to open the circuit...:) Anyway, I don't see much risk, either to equipment or the wallet, and certainly not the operator(that would be US).cheers,Douglas
