

---

Subject: Re: More piezo stuff - high order networks, etc.  
Posted by [Paul C.](#) on Wed, 09 May 2001 19:24:16 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

That's interesting. They weren't chirping though, so that's not it. I've only had two instances of burning the resistors internally mounted in the drivers. But it only happened twice and never happened again.

---