

---

Subject: Re: Thermionic four Pi's sound "horny"

Posted by [Wayne\\_Parham](#) on Fri, 31 Aug 2001 02:16:53 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I know we've exchanged some E-mails - but please refresh my memory. What did you do for a crossover? If you have not installed the appropriate crossover - as shown in the schematic - or if there is something wrong with them, particularly in the compensation network, you can expect the speaker system to perform poorly. The compensation network is very important and without it you will have a 15dB peak in the vocal overtone region. So examine your crossover network carefully.

---