

---

Subject: MD2001 - Good down to 1Khz; PSD2002 - Slightly higher

Posted by [Wayne Parham](#) on Sat, 15 Dec 2001 18:01:24 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I think you'll be OK with 1.2kHz crossover point, certainly if over 2nd or 3rd order. The MD2001 is good to 1kHz, the PSD2002 a little higher. I cross mine over at 1.6kHz third-order but 1.2kHz is probably OK if the horn loads there and the slope is high enough.

---