
Subject: Question for Wayne: Eminence Stock Xover
Posted by [Garland](#) on Sat, 15 Dec 2001 23:56:02 GMT

[View Forum Message](#) <> [Reply to Message](#)

Wayne, I just received the PX-bII 1k6 from Parts Express and noticed that it does not include R3 and C5 from your crossover schematic. I assume I need to add these so can you give me the ratings for the components: C5 is the 20uF cap and R3 is the 8 ohm resistor: both across the woofer of the Theater 4's. I did order the parts for the tweeter compensation, fortunately. One other question: Do you know if the inductors in the stock crossover are the exact same values as you've spec'ed in you crossover document:"Crossover Diagram 1600Hz"? Thanks!Garland