

---

Subject: Adire HE10.1 in AudioXpress

Posted by [Wayne Parham](#) on Wed, 16 Aug 2006 15:00:20 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I'll check the back issues and see, but as I recall the measurements clearly showed the tell-tale spiked dip you would expect from summing two out-of-phase sound sources. If I remember correctly, the problem was that this was reported in the magazine. The ugly response curve was shown in print. Adire explained the anomaly in the response curve by saying that the tweeter was connected out-of-phase, and discovered that the problem was their crossovers were mislabeled, so they were sent to AudioXpress that way. Adire was able to explain the problem to everyone's satisfaction in messageboards and what-not, but the ugly response curve had already been committed to ink in the AudioXpress magazine article.

---