

---

Subject: Maybe the horn? Microphone? Measurement environment? Could be lots of things.

Posted by [Wayne Parham](#) on Fri, 17 May 2002 06:49:15 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Try the measurement with a different horn flare. Try it with a different microphone. Try it with a different compression driver. And try it in different locations and from different measuring positions. Some trends will arise, and they will give an indication of what is causing what in the response.