

---

Subject: Re: Lathe turned horn for PSD2002  
Posted by [str8aro](#) on Thu, 23 May 2002 12:25:00 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

It wouldn't be too hard if you were already good at lathe work and had a lathe with the capacity for it. If you wanted to make a really deep one you could get into issues with the boring bar needed, but you'd also need a really big lathe so the boring bar probably wouldn't be such a big deal at that point... You do want to make sure you're not overloading the lathe, though. You can burn out bearings and other such fun things. John