

---

Subject: Re: Tolerance

Posted by [BillEpstein](#) on Tue, 16 Jul 2002 00:36:00 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Why don't you put the flange on the inside of the box so it, and it's screws, don't show. Add the thickness of the box to the port, of course. Just paint the inside edge of the hole black and put a little sealant under the flange.

---