

---

Subject: Re: sounds OK

Posted by [Wayne Parham](#) on Wed, 18 Dec 2002 07:32:20 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

unusual in that they are very tall. Because of this, standing waves develop along the long dimension, so driver and port position become important. You don't want either the port or the driver to fall on a  $1/4$  node or odd multiples, as it would develop ripples in response. My suggestion is to leave the port where it is shown in the plans.

---