

---

Subject: be george, he's got it!

Posted by [Sam P.](#) on Mon, 13 Jan 2003 10:50:01 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Ron, Good call on the crossover still seeing about the same load, even with the higher driver impedance. Are you using a R2 of 16ohms, and R1 of 25ohms, a la 12dB Pi Pad? Then substituting the higher z driver will likely reduce the attenuation present by maybe(?) 1.5dB's...you could probably "correct" for the difference by increasing R1 to 30 ohms. Otherwise, your HF MAY be a little hot. Sam

---