

---

Subject: Re: Impedance peak

Posted by [Wayne Parham](#) on Wed, 19 Feb 2003 17:44:00 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

An impedance peak of 13 ohms isn't terribly high, and is expected from a horn. There will be a few peaks near the flare frequency and its harmonics. There are also sometimes peaks caused by diaphragm mechanical resonance below the flare frequency, where the horn cannot load the diaphragm. To tame these peaks, and electrically match the driver better with the crossover, I

information.

---