

---

Subject: Re: Just slice them

Posted by [bmar](#) on Thu, 08 May 2003 17:18:35 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I dont know anyone who has ever cut the fins out. You just slice the fin right in the middle at the welded joint. If you want to get tricky you can fill the kerf with an elastomer like SikaFlex and repaint the horn. The metal will still be seperated and stress relieved yet invisable as a cut.Bill

---