
Subject: Re: Altec 511B Ringing Update
Posted by [Larry Moore](#) on Tue, 13 May 2003 17:10:29 GMT
[View Forum Message](#) <> [Reply to Message](#)

FWIW, when I had 511Bs, cutting the webs out completely and in particular that little vertical spacer right in front of where the driver mounts made as much, and probably more difference than "gapping the webs."
