

---

Subject: Top notch - You've got mail!

Posted by [Wayne Parham](#) on Sun, 25 May 2003 04:16:11 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

room, that's what would be there. Even if the corners were malformed, I'd still probably have them. But three of the four corners are immediately adjacent to entryways so it's a no-go. Lots of people run cornerhorns in positions where there are bay windows nearby or other similar situations. You don't need everything to be perfect to the inch, not even within several inches. Wavelengths are long for the bass, so variations that are measured in inches aren't much concern. It's just that if you don't have corners because of an entryway or very large obstruction then the boundary conditions aren't met.