
Subject: Re: Help on measurements, Thanks Bill
Posted by [JS](#) on Thu, 03 Jul 2003 10:40:08 GMT

[View Forum Message](#) <> [Reply to Message](#)

I don't think you have to use the test jig - you just need good connections, as noted. The test jig is just a way of making things a bit easier / neater. Are you measuring a resistor around 8 ohms? The program will have problems measuring values that are too far away from the reference resistor, iirc.
