

---

Subject: Re: Adjusting the capacitor value on the tweeter attenuator

Posted by [Wayne Parham](#) on Mon, 18 Aug 2003 03:08:19 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Your circuit is wired correctly, except that the stock cable uses 0.47uF for C1. But as you've noticed, the difference is pretty slight between C1 values of 0.33uF and 0.47uF in a circuit having these particular values of R1 and R2.

---