

---

Subject: Numero 6 heads too small

Posted by [Ubu](#) on Thu, 09 Oct 2003 10:14:21 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

the #6 heads are too small for the alpha 10 holes - not a tight fit.

---