

---

Subject: Re: They don't

Posted by [Adam](#) on Thu, 30 Oct 2003 20:55:03 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Yup. Thermal power handling may even be decreased slightly by horn loading. Particularly in the case of low frequency motors, cone motion is critical to the ventilation and cooling of the motor. Since horn loading dampens cone motion, this effect is somewhat retarded and can result in lower thermal power handling. Mechanical is a different story ;)Adam

---