

---

Subject: Compensation Network connection

Posted by [HaknHendrix](#) on Wed, 24 Mar 2004 01:53:05 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

About to solder the tweeter compensation resistors together, along with the capacitor. I hope this diagram is understandable, but want to make sure I've got it before I commit solder. The diagram below should represent 4 pairs of 16 ohm resistors in parallel serial combination. Top View of Resistor Pack

