

---

Subject: Re: Subwoofer project update

Posted by [hulkss](#) on Thu, 01 Apr 2004 00:45:27 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Tool up = Cost up = Price up. Chuffing sound may be an issue in a dipole bass speaker or in an application where the speaker is mounted backside out. Does Eminence believe that a .75" magnet vent could ever be audible or cause distortion in a closed back front horn cabinet?

---