
Subject: Re: Also while on the subject.

Posted by [James W. Johnson](#) on Mon, 19 Jul 2004 14:19:15 GMT

[View Forum Message](#) <> [Reply to Message](#)

Should I put anything else between the 2002 and H290? I noticed one of my horns does not lay perfectly flat, although it could cinch up when I bolt it on. Also this is odd but my H290s look different from the back and one is a black satin and the other is a flat black....they clearly came off different molds. I ordered another ...hopfully there is not a third mold!! ha ha!
